



LOURDES A. LEON GUERRERO
GOVERNOR (MAGA'HAGA)

JOSHUA F. TENORIO
LIEUTENANT GOVERNOR
(SIGUNDO MAGA'HAGA)

DEPARTMENT OF ADMINISTRATION

GENERAL SERVICES AGENCY

AHENSIAH SETBISION HINIRAT
148 ROUTE 1 SOUTH MARINE CORPS DRIVE, PITI, GU 96915
TELEPHONE: (671) 475-1707/1708
FAX: (671) 472-4217/1727
EMAIL: GSAPROUREMENT@GSADOA.GUAM.GOV
WEBSITE: WWW.GSA.DOA.GUAM.GOV



EDWARD M. BIRN
DIRECTOR (DIREKTOT)

BERNADINE C. GINES
DEPUTY DIRECTOR
(SIGUNDO DIREKTOT)

May 19, 2022

INVITATION FOR BID
GSA-020-22
CAMERA SYSTEM UPGRADE AND REPLACE SERVER SYSTEM
Bureau of Statistics Plans (for Department of Youth Affairs)

AMENDMENT #6

1. Amend page 36 of 37.

Remove from specification(s)

-Install 6 TRENDnet cameras DYA has on-hand and configured to the video surveillance system (three at LF2, Bldg, H 2nd floor, Intake, and Delta dayroom 1)

2. Amend and replace Addendum #7 with attached "Revised 05/20/22 Addendum #7."

All others remain unchanged.


CLAUDIA S. ACFALLE
Chief Procurement Officer

Please Print

Acknowledgement Copy (Re-Fax to GSA)

Received By: _____

Date: _____

Company Name: _____

Fax to: 475-1727 or 472-4217

Email to: gsaprourement@gsadoa.guam.gov

Department of Youth Affairs
#169 San Isidro St. Mangilao, Guam 96923
P.O. Box 23672, GMF Barrigada, Guam 96921
Tel: (671) 735-5010
Fax: (671) 734-7536

Department of Youth Affairs Scope of Work

Assessment and Diagnosis

Cameras						
Camera Label	Location	Operational	Model No.	IP Address and Ports	Login	Notes
Delta Dayroom 1	Above D-unit control room	Yes				
Foxtrot Hallway 01	Above north entrance/exit door, CJC Wing	Yes	GID10M-WIR	192.168.0.20 RTSP 554 ONVIF 80	Admin blank	
Foxtrot	General Population hallway	No	GID10M-WIR	192.168.0.33		Camera was removed
Foxtrot Control Room	F-Unit control room	Yes	GID20M-VVW	192.168.0.212 RTSP 554 ONVIF 80	Admin blank	Camera was removed
Foxtrot Hallway	F-Unit Dayroom above North exit/entrance	Yes				Camera has intermittent service.
PTZ Near Gym	Near West Perimeter fence; near bldg. G and the 40 ft. containers	No	PTZ Mobile Camera GSD36D-IRW			Camera was removed

Cameras						
Camera Label	Location	Operational	Model No.	IP Address and Ports	Login	Notes
Intake/Bldg. H 2nd floor stairway	Near office worker's desk	No	ACM-3701E			Camera was removed
Intake Entrance	Facing Security window	Yes				
Intake break room	East wall	Yes				
Intake Control Desk	Near YSS desk	Yes				
Intake Outdoor field	Between Gate 6 and Intake's north entrance/exit	Yes				
LF2/Test	Near LF2 east exit/entrance	Yes	ACTi D55	192.168.0.127 RTSP 7070, ONVIF 6002	admin 123456	Camera removed
IMFT Office	Ed Taitano's office; above doorway	No	ACM-3701E			
LF Classroom 2	Near world map	Yes				
LF classroom 3	Near teacher's office	Yes				
LF classroom 4	Classroom on west of building	Yes				
Galley 2	On east of dining area	Yes				
Echo Hallway-North wing	Near E-unit north exit/entrance door	Yes				
Echo Hallway-South wing	Near E-unit south entrance/exit door	Yes				
Echo Dayroom-North wing	Above entrance/exit to control room hallway	Yes				
Echo Dayroom-South wing	Near entrance/exit to control room hallway	Yes				

Scope of Work

Intake Building

1. Replace camera on second floor above office worker's desk on the drop ceiling.
2. Replace cameras on 1st floor near YSS desk and break room.
3. Replace outdoor cameras near security window and facing the courtyard.
4. Remove old G4S DVR and G4S Acer computer recording systems in Superintendent's office and consolidate all cameras into the brand new camera server.
 - a. The original G4S POE switch and TV monitor will be reused.
5. Label cables to correspond to connected camera and switches.
6. Replace cable routed through the 1st floor and 2nd floor of Intake/Bldg. H into the Superintendent's Office.
7. Setup the computer on the first floor to allow viewing of surveillance cameras.

Delta Unit

1. Replace junction LB covers outside the door to Delta Unit.
 - a. Use the replacement LB covers for the LB junctions for the cable.
 - b. Reattach the loose LB junction to the EMT pipe going in and out of the building in front of the door.
2. Replace cable going from Delta Unit to Intake Building.
3. Replace camera above control room.

LF2 Unit

1. Replace one camera in the counselor's office.
2. Replace camera in LF2's conference room.
3. Replace cable going from LF2 to Delta.

Foxtrot Unit

1. Install cameras in the Control room, Hallway in CJC, Hallway in general population.
 - a. When remounting the cameras ensure that the cable connector is sealed with a weatherproof seal as the conduits for the lines and the mounting boxes are right beneath the airducts which generates moisture and water.
2. Replace and install camera above north entrance/exit door of dayroom.
 - a. When remounting the cameras ensure that the cable connector is sealed with a weatherproof seal as the conduits for the lines and the mounting boxes are right beneath the airducts which generates moisture and water.
3. Replace cable from camera pole north of Foxtrot unit, through Foxtrot and to the gym. Route this cable to Intake building.
4. Replace and route the cable from the PTZ near gym to the Intake Building.

Echo Unit

1. Replace cameras in the north wing hallway, north wing dayroom, south wing hallway, and south wing dayroom.
2. Replace and route cable in Echo unit to Intake.

Liheng Famagu'on (LF)

1. Replace cameras in the 3 classrooms.
2. Replace and route cable in LF to Intake.

Perimeter

1. Install PTZ camera on pole mount near the gym.
 - a. Seal junction boxes for the PTZ cable and ensure that the cable will no longer be exposed to the elements.
 - b. Replace and route the cable from the PTZ near gym to the Intake Building.
2. Replace and route cable from DYA main gate camera to Intake.
 - a. Seal junction boxes for the camera cable and ensure that the cable will no longer be exposed to the elements.
3. Replace and route cable from Gate 2 PTZ camera (this camera is located in the parking lot; near the outdoor basketball court) to Intake.
 - a. Seal junction boxes for the PTZ cable and ensure that the cable will no longer be exposed to the elements.
4. Replace and route cable from the PTZ camera, near the north fence line (to the northwest of Echo unit), to Echo unit and then to Intake Building.
 - a. Seal junction boxes for the PTZ cable and ensure that the cable will no longer be exposed to the elements.

Director's Office

1. Setup remote viewing of surveillance system at Director's office.