



EDWARD M. BIRN  
Director (Direktot)  
EDITH C. PANGELINAN  
Deputy Director  
(Sigundo Direktot)

**DEPARTMENT OF  
ADMINISTRATION**  
DIPATTAMENTON ATMENESTRASION  
**GENERAL SERVICES AGENCY**

(Ahensian Setbision Hinirat)  
Telephone (Telifon): (671) 475-1707/1729 • Fax (Faks): (671) 472-4217/1727  
Email: [gsaprocurement@gsadoa.guam.gov](mailto:gsaprocurement@gsadoa.guam.gov)



LOURDES A. LEON GUERRERO  
Governor (Maga'håga)  
JOSHUA F. TENORIO  
Lt. Governor (Sigundo Maga'låhi)

November 4, 2019

**Invitation or Bid: GSA-055-19**  
**14 Passenger, A.D.A Compliant GRTA Buses**  
For: Guam Regional Transit Authority

**Amendment #4**

1. Amend Bid Opening Date:

**From:** November 05, 2019 at 11:00 a.m. **To Now Read:** November 15, 2019 at 2:00 p.m.

2. Amend **Specification** on Page 49 of 74: **SAFETY EQUIPMENT: [Fire Extinguishers]**

**From:** Ten (10) 5 lb. 2A:10B:C metal body fire extinguishers, ABC dry chemical, with anodized aluminum valve, wall bracket, hose and nozzle mounted on the stanchion next to the driver but not impede the ingress and egress of passengers

**To Now Read:** One (1) 5 lb. fire extinguisher per bus, 2A:10B:C metal body fire extinguishers, ABC dry chemical, with anodized aluminum valve, wall bracket, hose and nozzle mounted on the stanchion next to the driver but not impede the ingress and egress of passengers.

3. Amend **Specification** on Page 49 of 74: **SAFETY EQUIPMENT: [First Aid Kit]**

**From:** Ten (10) First Aid Kits installed next to driver curbside window forward of the passenger entrance door conform to Department of Transportation (DOT) and Occupational Safety and Health Administration (OSHA) requirements.

**To Now Read:** One (1) first aid kit per bus, installed next to driver curbside window forward of the passenger entrance door conform to Department of Transportation (DOT) and Occupational Safety and Health Administration (OSHA) requirements

4. Amend **Specification** on Page 49 of 74: **SAFETY EQUIPMENT: [Blood Borne Pathogen Kits]**

**From:** Ten (10) Blood Borne Pathogen Kits installed below the First Aid Kits Decals indicating the locations of the First Aid & Blood Borne Pathogen Kits shall be placed on the dashboard above or window sill of the driver curbside window

**To Now Read:** One (1) blood borne pathogen kit per bus, installed below the First Aid Kits Decals indicating the locations of the First Aid & Blood Borne Pathogen Kits shall be placed on the dashboard above or window sill of the driver curbside window

5. Amend **Specification** on Page 49 of 74: **SAFETY EQUIPMENT: [Emergency Reflectors]**

**From:** Ten (10) Emergency reflectors containing three (3) reflective warning triangles installed behind Driver seat

**To Now Read:** One (1) emergency reflector containing three (3) reflective warning triangles installed behind Driver seat

6. Amend **Specification** on Page 49 of 74: **SAFETY EQUIPMENT: [Wheel Chocks]**

**From:** Ten (10) set of two (2) Wheel Chocks - heavy-duty solid molded

**To Now Read:** One (1) set of two (2) wheel chocks per bus - heavy-duty solid molded

\*All Others Remain the Same.

Please Print  
Acknowledgement Copy (Re-Fax to GSA)

Received by: \_\_\_\_\_

Date: \_\_\_\_\_

Company Name: \_\_\_\_\_

Fax To: 475-1727 or 472-4217

Email To: [gsaprocurement@gsadoa.guam.gov](mailto:gsaprocurement@gsadoa.guam.gov)



Claudia S. Acfalle  
Chief Procurement Officer